

NAITF Plugfest Equipment List

Company	Equipment	S/W Version	Total Name	H/W is Mobile?	Part 6 (VT)	Part 6 (Working Set)	Part 9 (TECU)	Part 10 (TC)	Part 10 (Working Set)	Part 10 (FMIS)	Part 12 (Diag)	Part 13 (FS)	Part 13 (Client)
AGCO-ATS	AED AirMax	1.2	AGCO-ATS: AED AirMax (v 1.2)	Yes	None	Spec 2	None	None	FDIS.2	None	No	None	None
AGCO-ATS	AED Sprayer	1.2	AGCO-ATS: AED Sprayer (v 1.2)	Yes	None	Spec 2	None	None	FDIS.2	None	No	None	None
AGCO-ATS	GTA Console II	1.6.5	AGCO-ATS: GTA Console II (v 1.6.5)	Yes	Spec 2	None	None	FDIS.2	None	None	No	FDIS	None
AGCO-ATS	GTA FMIS	?	AGCO-ATS: GTA FMIS (v ?)	Yes	None	None	None	None	None	FDIS.1	No	None	None
AGCO-ATS	SGIS	?	AGCO-ATS: SGIS (v ?)	Yes	None	None	None	None	None	FDIS.1	No	None	None
AGCO-Hesston	Round Baler WSM	2.13	AGCO-Hesston: Round Baler WSM (v 2.13)	Yes	None	Spec 2	None	None	None	None	No	None	None
AGCO-Hesston	Square Baler WSM	2.4	AGCO-Hesston: Square Baler WSM (v 2.4)	Yes	None	Spec 2	None	None	FDIS.1	None	No	None	FDIS
Agtron Enterprises	Airseeder ECU	6.64	Agtron Enterprises: Airseeder ECU (v 6.64)	Yes	None	Spec 2	None	None	FDIS.2	None	No	None	None
Agtron Enterprises	B/W VT	1.12	Agtron Enterprises: B/W VT (v 1.12)	Yes	Spec 2	None	None	Partial	None	None	No	None	None
Agtron Enterprises	Planter ECU	1.64	Agtron Enterprises: Planter ECU (v 1.64)	Yes	None	Spec 2	None	None	FDIS.2	None	No	None	None
DICKEY-john Corp	IntelliAg 10" (A1+) Terminal	1.6.5	DICKEY-john Corp: IntelliAg 10" (A1+) Terminal	Yes	Spec 2	None	None	FDIS.2	None	None	No	FDIS	None
DICKEY-john Corp	IntelliAg 5" (A2) Terminal	4.45	DICKEY-john Corp: IntelliAg 5" (A2) Terminal	Yes	Spec 2	None	Class 1	None	None	None	No	None	None
DICKEY-john Corp	IntelliAg LIQIV with Member Modules	P04.XX	DICKEY-john Corp: IntelliAg LIQIV with Member Modules	Yes	None	Spec 3	None	None	FDIS.2	None	No	None	FDIS
DICKEY-john Corp	IntelliAg PDC with Member Module	P04.XX	DICKEY-john Corp: IntelliAg PDC with Member Module	Yes	None	Spec 3	None	None	FDIS.2	None	No	None	FDIS
DICKEY-john Corp	IntelliAg TECU (1)	3.03	DICKEY-john Corp: IntelliAg TECU (1)	Yes	None	Spec 2	Class 1	None	None	None	No	None	None
John Deere IVS	GS2 1800 (1.2)	1.2.61	John Deere IVS: GS2 1800 (1.2) (v 1.2.61)	Yes	Spec 2	None	None	None	None	None	Yes	Partial	None
John Deere IVS	GS2 1800 (2.0)	2.0.304	John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	Yes	Spec 2	None	None	None	None	None	Yes	Partial	None
John Deere IVS	GS2 2600	2.3.+	John Deere IVS: GS2 2600 (v 2.3.+)	Yes	Spec 3	None	None	Partial	None	None	Yes	Partial	None
John Deere Seeding	ISO Planter	4.0	John Deere Seeding: ISO Planter (v 4.0)	Yes	None	Spec 2	None	None	FDIS.1	None	No	None	None
John Deere Seeding	ISO Air Cart	1.0	John Deere Seeding: ISO Air Cart (v 1.0)	Yes	None	Spec 2	None	None	None	None	No	None	None
John Deere Seeding	ISO Blockage	1.0	John Deere Seeding: ISO Blockage (v 1.0)	Yes	None	Spec 2	None	None	FDIS.1	None	No	None	None
NTech/Microfirm	RT200ISO - Sensor/Rate commander	0.5.10	NTech/Microfirm: RT200ISO - Sensor/Rate commander	Yes	None	Spec 2	None	None	FDIS.1	None	No	None	None
Parker Vansco	Small B/W VT	1.0.0.13	Parker Vansco: Small B/W VT (v 1.0.0.13)	Yes	Spec 2	None	None	None	None	None	No	None	None
Parker Vansco	Small Color VT	0.4.49.10	Parker Vansco: Small Color VT (v 0.4.49.10)	Yes	Spec 2	None	None	None	None	None	No	None	None
Parker Vansco	Variable Rate Seeder Controller	5.0.1	Parker Vansco: Variable Rate Seeder Controller	Yes	None	Spec 4	None	None	FDIS.2	None	No	None	FDIS
Raven Industries Inc	AutoBoom	1.2	Raven Industries Inc: AutoBoom (v 1.2)	Yes	None	Spec 2	None	None	None	None	No	None	None
Raven Industries Inc	Product Controller	beta	Raven Industries Inc: Product Controller	Yes	None	Spec 2	None	None	None	None	No	None	None
TeeJet Technologies	IC34.2	1.10G	TeeJet Technologies: IC34.2 (v 1.10G)	Yes	None	Spec 2	None	None	FDIS.2	None	No	None	None
TeeJet Technologies	Power Link 600	0.11	TeeJet Technologies: Power Link 600 (v 0.11)	Yes	Spec 2	None	None	None	None	None	No	None	None
TeeJet Technologies	Power Link 640	1.18A	TeeJet Technologies: Power Link 640 (v 1.18A)	Yes	Spec 2	None	None	Partial	None	None	No	None	None
Vector CANtech	CANoe.ISO11783	5.0	Vector CANtech: CANoe.ISO11783 (v 5.0)	Yes	Spec 3	Spec 3	None	None	None	None	No	None	None

**NAITF Plugfest
Equipment Test Matrix**

		Tuesday, November 11, 2008							
Station	Equip.	8:00 AM	9:00 AM	10:00 AM	11:00 AM	1:00 PM	2:00 PM	3:00 PM	4:00 PM
1	VT	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS
	ECUs		Agtron Enterprises	TeeJet Technologies	John Deere Seeding	DICKEY-john Corp	Raven Industries Inc	NTech/Microfirm	Parker Vansco
2	VT	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises
	ECUs		DICKEY-john Corp	AGCO-Hesston	TeeJet Technologies	John Deere Seeding	Parker Vansco	Raven Industries Inc	NTech/Microfirm
3	VT	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp
	ECUs		NTech/Microfirm	Agtron Enterprises	AGCO-Hesston	TeeJet Technologies	AGCO-ATS	Parker Vansco	Raven Industries Inc
4	VT	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS
	ECUs		Parker Vansco	NTech/Microfirm	Agtron Enterprises	AGCO-Hesston	TeeJet Technologies	AGCO-ATS	DICKEY-john Corp
5	VT	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco
	ECUs		Raven Industries Inc	DICKEY-john Corp	NTech/Microfirm	Agtron Enterprises	AGCO-Hesston	TeeJet Technologies	John Deere Seeding
6	VT	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies
	ECUs		John Deere Seeding	Raven Industries Inc	DICKEY-john Corp	NTech/Microfirm	Agtron Enterprises	AGCO-Hesston	AGCO-ATS

**NAITF Plugfest
Equipment Test Matrix**

		Wednesday, November 12, 2008			
Station	Equip.	8:00 AM	9:00 AM	10:00 AM	11:00 AM
1	VT	AGCO-ATS	AGCO-ATS	AGCO-ATS	AGCO-ATS
	ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs
2	VT	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises	Agtron Enterprises
	ECUs	AGCO-ATS	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs
3	VT	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp	DICKEY-john Corp
	ECUs	John Deere Seeding	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs
4	VT	John Deere IVS	John Deere IVS	John Deere IVS	John Deere IVS
	ECUs	Raven Industries Inc	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs
5	VT	Parker Vansco	Parker Vansco	Parker Vansco	Parker Vansco
	ECUs	AGCO-ATS	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs
6	VT	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies	TeeJet Technologies
	ECUs	Parker Vansco	Multiple VTs/ECUs	Multiple VTs/ECUs	Multiple VTs/ECUs

Equipment AGCO-ATS: GTA Console II (v 1.6.5)

Equipment	General Result / Comments
Agtron Enterprises: Planter ECU (v 1.64)	TC only shows 9 DET's. They want 30x 1 for each row
TeeJet Technologies: IC34.2 (v 1.10G)	TC client doesn't come up first time-rebooted ECU & TC works. TC sending 100.0L/ha, but it controls at 1.00 l/ha
John Deere Seeding: ISO Planter (v 4.0)	error frame when plugging in their ECU. Resolution wrong on JD DDI for planter population (off by 100x)
Raven Industries Inc: AutoBoom (v 1.2)	VT problem-when ECU causes alarm mask, VT goes to wrong WS after ACK
Raven Industries Inc: Product Controller (v beta)	selected spd not working-Recv Grnd Spd J1939
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	no AGCO problems
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	No AGCO problems

Equipment

AGCO-ATS: GTA FMIS (v ?)

Equipment

General Result / Comments

AGCO-ATS: GTA FMIS (v ?)	writes g-s2 files but cannot read gs2 files
AGCO-ATS: SGIS (v ?)	* "Shape file converter" manual workaround required --> * reads and writes files from g-s2

Equipment

Agtron Enterprises: B/W VT (v 1.12)

Equipment	General Result / Comments
DICKY-john Corp: IntelliAg TECU (1) (v 3.03)	no pool upload
AGCO-Hesston: Round Baler WSM (v tbd)	pool upload fine can not parse color bmp
AGCO-ATS: AED Sprayer (v 1.2)	pool uploads fine can not parse color bmp ERR in vt
TeeJet Technologies: IC34.2 (v 1.10G)	eev does not seem to respond after the UT responds with 0 versions available. We seem to be missing a proper response to ECU but Err in VT are unsure about what it is.
Raven Industries Inc: AutoBoom (v 1.2)	pool uploads fine does not find workset Err in VT
Raven Industries Inc: Product Controller (v beta)	pool uploads fine does not find workset Err in vt
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	does not parse pool at all Err in vt
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	pool loads does not find workset active mask Err in vt

Equipment

Agtron Enterprises: Airseeder ECU (v 6.64)

Equipment

General Result / Comments

AGCO-ATS: GTA Console II (v 1.6.5)	task controller was showing valve presentation objects when none are sent
DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)	ETP packets out of order failed trasfer Agtron fixed ETP xfer: Pool loads and VT functions ok
DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	ok √ OGI pool
John Deere IVS: GS2 2600 (v 2.3.+)	Pool loads, TC crasked with 10 elements or more
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	ok
Parker Vansco: Small Color VT (v 0.4.49.10)	ok
Parker Vansco: Small B/W VT (v 1.0.0.13)	ok
TeeJet Technologies: Power Link 640 (v 1.18A)	ok
TeeJet Technologies: Power Link 600 (v 0.11)	ok

Equipment

TeeJet Technologies: Power Link 600 (v 0.11)

Equipment

General Result / Comments

John Deere Seeding: ISO Planter (v 4.0)	VSS does not scale down (SV only)
Raven Industries Inc: AutoBoom (v 1.2)	VT freeze while unpacking the pool
DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)	Minor color-mapping issue in VVS VT docs not handle transparency in bitmaps correct
DICKEY-john Corp: IntelliAg LIQIV with Member Modules (v P04.XX)	Pool too big for VT (215kb)
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	Minor color-scaling issues VT draws dashed lines as solid
Agtron Enterprises: Planter ECU (v 1.64)	Minor font-scaling issue VT only supports a subset of the font sizes this seems to confuse the VVS
AGCO-Hesston: Round Baler WSM (v 2.13)	Pool uploaded ok. Alarm masks displayed ok VT froze when trying to show datamask. Pool contains colors.
AGCO-Hesston: Square Baler WSM (v 2.4)	Not tested
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	ok

Equipment

TeeJet Technologies: Power Link 640 (v 1.18A)

Equipment	General Result / Comments
AGCO-Hesston: Round Baler WSM (v 2.13)	Ok. Minor scaling and unit issue in VVS
AGCO-Hesston: Square Baler WSM (v 2.4)	TC is not requesting default data variables
John Deere Seeding: ISO Planter (v 4.0)	Rejected by VT. Possibly due to a font attrituge object with font type=255 (proprietary)
Raven Industries Inc: AutoBoom (v 1.2)	Ok when VT at address 2616. If the VT is forced to address 8016 it does not respond to TP/ETP messages. Problem caused by VT
Raven Industries Inc: Product Controller (v beta)	ok
DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)	ok
DICKEY-john Corp: IntelliAg LIQIV with Member Modules (v P04.XX)	Error writing to the file server. TC ok, but indication in VVS only show TC when TC is sending request messages (States msg is not enough)
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	OK TC accepts device description. Logging only with GPS (We did not have GPS connected)
Agtron Enterprises: Planter ECU (v 1.64)	OK
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	VT ok TC pad uploaded but not functioned FileServer not working

Equipment

TeeJet Technologies: IC34.2 (v 1.10G)

Equipment

General Result / Comments

AGCO-ATS: GTA Console II (v 1.6.5)	Need to upload new device discription. When units/lang. change lang. pgm
AGCO-ATS: GTA Console II (v 1.6.5)	Task is sending 100 l/ha and we are controlling to 57 l/ha. (we are targeting 1 decimal offset?)
AGCO-ATS: GTA Console II (v 1.6.5)	we set rate to 10,000 l/ha and we controlled 100 l/ha. Auto manual softkey not displaying correctly
AGCO-ATS: GTA Console II (v 1.6.5)	Softkeys defined iv GTA with no command functions. Rather than softkeys as functions-name as nolls. Scroll to object on screens in set-up. GTA will eliminate the scroll through softkeys and expect to scroll to input fields in the display.
AGCO-ATS: GTA Console II (v 1.6.5)	when operating to task controller, turning on booms on screen will not always turn on the boom sections. But master always appears Boom Section Control!
Agtron Enterprises: B/W VT (v 1.12)	Does not see C34II. Not responding to PGN request EE
Agtron Enterprises: B/W VT (v 1.12)	brand new- Get to get versions, agrtron responses none, we ask for TASC Controller version, Agtron responds version 0, we send status msg then we reclaim address request.
DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	The softkeys do not have borders. Auto/manual icons do not show up. Sprayer icon is missing/speed graphics did not show up. 16 color display shows orange as yellow.
DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)	running TCU, sprayer, planter, 2nd sprayer all on same bus
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	D & E appear but have no function
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	In transport mode, the softkeys are still displayed with no functions (need to be knull)
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	The data mask is not set up to scroll to it.

Equipment

TeeJet Technologies: IC34.2 (v 1.10G)

Equipment

General Result / Comments

John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	Boom width from jeejet to GS2 is not transferring. JD showing 14.8' for all. We had 200", 250", 250", 200", 200"
John Deere IVS: GS2 2600 (v 2.3.+)	We are not following task controller time outs. With task controller on line, causes issues w/pcpt modules???
Parker Vansco: Small Color VT (v 0.4.49.10)	Page forward button does not work
Parker Vansco: Small B/W VT (v 1.0.0.13)	Graphics for transfer mode has no numbers. Tank graphics cuts off MPH text.

Equipment

John Deere IVS: GS2 1800 (2.0) (v 2.0.304)

Equipment

General Result / Comments

NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	OP loads text on softkeys is small
AGCO-Hesston: Round Baler WSM (v 2.13)	OP loads. Might have issue with alarm mark and stray softkey Edge spacing could have issues. Should not be tied to units. Agco issue w/
AGCO-Hesston: Square Baler WSM (v 2.4)	Small text strings File server error-file server not sending status message
TeeJet Technologies: IC34.2 (v 1.10G)	Softkeys not nulled when not used
AGCO-ATS: AED AirMax (v 1.2)	No issues
DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)	
Raven Industries Inc: Product Controller (v beta)	Object pool did not load. Invalid application error. Screen capture taken
15 ECUs	After about 15 working sets would show up, the GS3 would lock up, then on the next boot cycle, 1 would get an "Internal memory full" message. Total internal memory consumed about 45 mb.
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	Seems the ISO File Server is not running. The file server button does not slow up. Seems to not be sending the status message
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	OP looks good

Equipment John Deere IVS: GS2 2600 (v 2.3.+)

Equipment	General Result / Comments
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	Sensor data to rate controller OP looks good Task controller reports not compatible ("Sensor")
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	File server is running, but does not respond to a save. This seems to be caused by the "change current directory message."
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	Get an error "task controller" not valid message seems it is because they are reporting as Fertilizer Class
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	Change device class and still not working
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	tested Aux controls and everything seemed to work fine
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	TC works w/ 3.0.1 version instead of 5.0.1
Agtron Enterprises: Airseeder ECU (v 6.64)	GS2 crashes when they send 12 VR tasks controller sections. 9 sections work fine
AGCO-Hesston: Square Baler WSM (v 2.4)	Fileserver-does not work if they are looking for the root folder
TeeJet Technologies: IC34.2 (v 1.10G)	Section widths show 14.8' for all. Setup for 200, 250, 250, 200, 200. Change to 120, 240, 120, 240, 120. Still 14.8". *Fixed values for Task Controller Pool 4.5m
AGCO-ATS: AED AirMax (v 1.2)	No issues loading
DICKEY-john Corp: IntelliAg LIQIV with Member Modules (v P04.XX)	Upload VT Ver 2 & 3 aux controls. May have 1 old selection & 1 new. DJ reporting already assigned Shows as 80' 1 section when has 6 section under controls (10, 10, 20, 20, 10, 10)
DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)	OP OK. TC upload looks ok. No screen to show on screen

Equipment John Deere IVS: GS2 2600 (v 2.3.+)

Equipment General Result / Comments

Raven Industries Inc: AutoBoom (v 1.2)	OK
AGCO-ATS: AED Sprayer (v 1.2)	OP ok, still trouble w/ TC. Impl not compatible. Show - - - in description No sections for controller. Would come from other controller.

Equipment

DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)

Equipment

General Result / Comments

NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	Color object pool loaded okay. Task controller logged 4 ddi's. FarmWorks imported data and displayed correct units.
Agtron Enterprises: Planter ECU (v 1.64)	Object pool uploaded and displayed
TeeJet Technologies: IC34.2 (v 1.10G)	No issues
John Deere Seeding: ISO Planter (v 4.0)	Planter sticks on initializing screen Task controller did not show rates on screen
John Deere Seeding: ISO Blockage (v 1.0)	Object placement issues

Equipment

DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)

Equipment

General Result / Comments

NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	Mono pool loaded. Only has 256 color or b/w pool. Some B/W BMPS. Some color lines and backgrounds did show up.
Agtron Enterprises: Planter ECU (v 1.64)	object pool uploaded after ECU software adjustment of message timing. Tractor ECU messaging might have caused too high of bus load. Object pool check failed an object 17968.
AGCO-ATS: AED Sprayer (v 1.2)	Object pool uploaded and displayed. Smallest font size used on many strings but spacing between objects was not sufficient to avoid clipping.
TeeJet Technologies: IC34.2 (v 1.10G)	VT did not draw softkey borders
Parker Vansco: Variable Rate Seeder Controller (v 5.0.1)	Object pool uploaded. "On/Off" soft key was not functional. Soft key message with correct ID was sent out. After turning the function "off" with canoe VT, the 5" terminal worked okay.
Raven Industries Inc: AutoBoom (v 1.2)	Object pool uploaded, but main work object 1000 has an error
John Deere Seeding: ISO Planter (v 4.0)	Softkey did not scale correctly
John Deere Seeding: ISO Blockage (v 1.0)	Softkey did not scale correctly Row #'s covered by bar graphs

Equipment

DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)

Equipment

General Result / Comments

Agtron Enterprises: B/W VT (v 1.12)	pool does not load
Parker Vansco: Small B/W VT (v 1.0.0.13)	color mapping issue with silver --> black In work is all black on black background
Parker Vansco: Small Color VT (v 0.4.49.10)	ok
TeeJet Technologies: Power Link 640 (v 1.18A)	ok
TeeJet Technologies: Power Link 600 (v 0.11)	color mapping issue transparent shows as white in work status is always white In work/out work both map to open
John Deere IVS: GS2 2600 (v 2.3.+)	vt-ok tc-appears that pool transfer ok
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	vt-ok does not do Aux v2 assign

Equipment

DICKEY-john Corp: IntelliAg PDC with Member Module (v P04.XX)

Equipment

General Result / Comments

Parker Vansco: Small B/W VT (v 1.0.0.13)	working set object not found
Parker Vansco: Small Color VT (v 0.4.49.10)	not enough memory

Equipment

DICKEY-john Corp: IntelliAg LIQIV with Member Modules (v P04.XX)

Equipment

General Result / Comments

TeeJet Technologies: Power Link 640 (v 1.18A)	Worked. Summary very small. TC only request data 6 seconds (icon goes away)
TeeJet Technologies: Power Link 600 (v 0.11)	Too large
John Deere IVS: GS2 2600 (v 2.3.+)	Aux function shown unable to map w/ canoe input

Equipment

Raven Industries Inc: Product Controller (v beta)

Equipment

General Result / Comments

Parker Vansco: Small Color VT (v 0.4.49.10)	controller did not load 16 color picture graphics. Some of text is clipped.
Parker Vansco: Small B/W VT (v 1.0.0.13)	Upload on display ok. Small device description pool upload to TC- ok
AGCO-ATS: GTA Console II (v 1.6.5)	upload and display ok. Small device description pool upload to TC ok
Agtron Enterprises: B/W VT (v 1.12)	Upload object pool without errors but did not display
John Deere IVS: GS2 2600 (v 2.3.+)	Upload object pool without errors, control ECU did not start TC client connection
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	Upload object pool without errors on 2nd attempt. Loaded with errors on 1st attempt

Equipment

Raven Industries Inc: AutoBoom (v 1.2)

Equipment

General Result / Comments

Parker Vansco: Small B/W VT (v 1.0.0.13)	pool load fail-invalid color
Parker Vansco: Small Color VT (v 0.4.49.10)	Pool load successful-flashing not working
TeeJet Technologies: Power Link 640 (v 1.18A)	Successful upload & function No response from VT on pool request to send (when VT at address x 80)
AGCO-ATS: GTA Console II (v 1.6.5)	Successful upload & function. Alarm ACK did not return display to original mask shown before alarm occurred.
Agtron Enterprises: B/W VT (v 1.12)	Upload object pool without errors but did not display
DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	Object pool loaded but had errors
John Deere IVS: GS2 2600 (v 2.3.+)	Object pool loaded without errors. Display OK
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	Object pool loaded without errors. Display OK

Equipment

John Deere Seeding: ISO Blockage (v 1.0)

Equipment

General Result / Comments

TeeJet Technologies: Power Link 640 (v 1.18A)	Flashes ISO connect pic not connecting
AGCO-ATS: GTA Console II (v 1.6.5)	"1" & "2" are too big pic 22 SN string "Population" too big
Agtron Enterprises: B/W VT (v 1.12)	Could not parse object pool Probably issue w/ the display
DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	Softkey string issue (?) number on clutch buttons not visible highlight color same as background numbers on blockage sensors not (?) text on tabs not showing up
DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)	numbers on clutch buttons cut off SN cut off no borders on tabs "population" and "single rank" text gets cut off on country page "Bin level snsr" valve loads strange

Equipment

John Deere Seeding: ISO Planter (v 4.0)

Equipment

General Result / Comments

TeeJet Technologies: Power Link 600 (v 0.11)	Picture scale on warning. Working set button does not scale. Got screen shots. Softkey not sealing, run page clean. Drive section setup w/off.
TeeJet Technologies: Power Link 640 (v 1.18A)	not connecting. Says initializing. Then ISO connector pic. Rejected by VT possibly due to prep font attribute 0x04e4
AGCO-ATS: GTA Console II (v 1.6.5)	Sends error frame when plugging in no around speed connects pic text not fitting pic 20" (seeds/ha)" not fit Resolution of set point-x1000
Parker Vansco: Small B/W VT (v 1.0.0.13)	Not sealing pic on warning not sealing working set scaling font setup is bad
Parker Vansco: Small Color VT (v 0.4.49.10)	Same
???	Working set icons only text looked good
DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)	tab buttons have no border Stuck on "initializing screen" got target rate from tc no scaling issue 2 times seed pulses on startup V10 DDI reported back for target or action
DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	softkey scaling issue only

Equipment

Parker Vansco: Small B/W VT (v 1.0.0.13)

Equipment

General Result / Comments

Raven Industries Inc: AutoBoom (v 1.2)	pool load fail-invalid color
DICKEY-john Corp: IntelliAg PDC with Member Module (v P04.XX)	working set object missing
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	Need a b/w object pool but otherwise works very well
Agtron Enterprises: Planter ECU (v 1.64)	fixed
AGCO-Hesston: Round Baler WSM (v 2.13)	invalid color
TeeJet Technologies: IC34.2 (v 1.10G)	speed text overlap travel mode speedometer (missing labels) overlap w/numeric field with graphics rendering font large?
John Deere Seeding: ISO Planter (v 4.0)	scaling problem

Equipment

Parker Vansco: Small Color VT (v 0.4.49.10)

Equipment

General Result / Comments

John Deere Seeding: ISO Planter (v 4.0)	scaling issues
Raven Industries Inc: AutoBoom (v 1.2)	"calibrating" should be flashing
Raven Industries Inc: Product Controller (v beta)	need 16-bit icons color
DICKEY-john Corp: IntelliAg PDC with Member Module (v P04.XX)	not enough memory
DICKEY-john Corp: IntelliAg TECU (1) (v 3.03)	works well
NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)	very nice!
Agtron Enterprises: Planter ECU (v 1.64)	works as expected
AGCO-Hesston: Square Baler WSM (v tbd)	works well round bailer value outside min & max is displayed as 0, should display actual value
TeeJet Technologies: IC34.2 (v 1.10G)	soft key ID issue (their next page button doesn't work)

Equipment

NTech/Microfirm: RT200ISO - Sensor/Rate commander (v 0.5.10)

Equipment

General Result / Comments

DICKEY-john Corp: IntelliAg 5" (A2) Terminal (v 4.45)	Need to download 16 color pool. Downloaded B/W screen
DICKEY-john Corp: IntelliAg 10" (A1+) Terminal (v 1.6.5)	None
John Deere IVS: GS2 2600 (v 2.3.+)	Very small on softkeys need start/stop shape change
John Deere IVS: GS2 1800 (1.2) (v 1.2.61)	very small text on softkeys
John Deere IVS: GS2 1800 (2.0) (v 2.0.304)	very small text on softkeys
Parker Vansco: Small B/W VT (v 1.0.0.13)	Need improved BW mapping
Parker Vansco: Small Color VT (v 0.4.49.10)	No issues
TeeJet Technologies: Power Link 640 (v 1.18A)	No issues
TeeJet Technologies: Power Link 600 (v 0.11)	Need to use white background for BW screen Edit icon needs outline on pencil Edit line needs differentiated in BW
AGCO-ATS: GTA Console II (v 1.6.5)	No issues
Agtron Enterprises: B/W VT (v 1.12)	Loaded pool did not find Actine Mask (known issue w/ VT)

NAITF Plugfest
Information Sheet

Equipment

Equipment

General Result / Comments

Equipment	General Result / Comments